## Twister -the leg connector





Needed accessories for one set of Twister:


5 pcs. of suited mounting screws. Ø5mm screw, CSK, head diameter <10,30mm.

1 pce. of leg – any type metal or wood. Leg diameter at the Twister link plate <53mm.


M8 thread - length from 15mm to 22 mm – metal or wood leg.








Twister operates from a 90° angle to a 70° angle –  $20^{\circ}$  of steepless adjustment.








Step #2 – Place the linkplate on top of the leg.

Step #3 – Tighten the leg and linkplate onto the mounting plate. Adjust and tighten in the desired angel.



Tip : Use the indicators on the top of the mounting plate in order to make a precise positioning of the leg. Indicated by the green arrow.



Use the following measurements when pre-drilling.

